To: J Matthewson From: J Wiens

Acting Department Manager Environmental Specialist
Licensing and Environmental Licensing and Environmental

Assessment Assessment

Manitoba Hydro Manitoba Hydro

File: MMTP_CON_FA594 Date: November 30, 2021

MMTP_CON_FA595

Reference: Field Survey Summary – MMTP Access Management OBJECTIVE

A site visit was made of MMTP transmission project to inspect effectiveness of access controls in the post-construction phase. This was intended to fulfill requirements of Section 4.8.1 of the MMTP Environmental Monitoring Plan.

METHODS

A site visit was made by vehicle on October 26th and November 26th, 2021. The site was surveyed by vehicle and by foot, with photographs taken at relevant locations All health and safety protocols were adhered to including use of PPE. A review of the Operational Access Management Plan and MMTP landowner complaint registry was also conducted.

RESULTS

An MMTP Operational Access Management Plan was approved by the Province of Manitoba on April 14th, 2021 and permitted several access points on Crown Lands. A review of the MMTP landowner complaint registry showed all fences and access controls had been installed and that no outstanding landowner access concerns remained.

Access inspections were made of 35 sites. Inspection sites were focused on areas that made new or improved access. These were primarily in forested or natural areas. The following access management plan points were visited:

Access	Controls in place	Comments	Concerns
Management			
Point			
229	Gate installed		No concerns
230	Gate installed		No concerns
255	Boulders installed	Landowner has moved boulders to	No concerns
		allow construction access.	
256	Fence and gate installed		No concerns
282	Gate installed		No concerns
283	No controls required	Wetland area. Little visible use.	No concerns
284	Gate installed		No concerns
285	Existing fence and gate		No concerns
294	Gate installed		No concerns
300	Gate installed		No concerns
305	Fence and gate installed		No concerns
306	Fence and gate installed		No concerns
317	Gate installed		No concerns
318	Fence and gate installed		No concerns

335	Cultivated field		No concerns
344	Fence and gate installed		No concerns
346	No change to pre-existing access		No concerns
351	Cultivated field		No concerns
352	Fence present		No concerns
359	Gate installed		No concerns
360	Gate installed		No concerns
380	Fence and gate installed		No concerns
381	Fence and gate installed		No concerns
385	Gate installed		No concerns
386	Gate installed		No concerns
401	No controls required	Little visible use	No concerns
402	No controls required	Little visible use	No concerns
405	No controls required	Some vehicle traffic present	No concerns
406	No controls required	Some vehicle traffic present	No concerns
420	No controls required	Little visible use	No concerns
421	Gate and fence installed		No concerns
440	Fence installed		No concerns
441	No controls required	Landowner manages approach	No concerns
473	No controls required	Little visible use	No concerns
474	No controls required	No visible use	No concerns


RECOMMENDATIONS AND CHANGES

As there are no concerns identified, no further access related work is required. Photos of sites are included below.

PHOTOS



Access Management Point 229



Access Management Point 230

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 4 of 20



Access Management Point 255



Access Management Point 256



Access Management Point 282

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 6 of 20 $\,$



Access Management Point 283



Access Management Point 284

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 7 of 20



Access Management Point 285



Access Management Point 294

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 8 of 20 $\,$



Access Management Point 300



Access Management Point 305

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 9 of 20 $\,$



Access Management Point 306



Access Management Point 317

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 10 of 20



Access Management Point 318



Access Management Point 335

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 11 of 20



Access Management Point 344



Access Management Point 346

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 12 of 20 $\,$



Access Management Point 351



Access Management Point 352

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 13 of 20 $\,$



Access Management Point 359



Access Management Point 360

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 14 of 20



Access Management Point 380




Access Management Point 381

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 15 of 20



Access Management Point 385



Access Management Point 386

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 16 of 20



Access Management Point 401



Access Management Point 402

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 17 of 20



Access Management Point 405



Access Management Point 406

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 18 of 20 $\,$



Access Management Point 420



Access Management Point 421

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 19 of 20 $\,$



Access Management Point 440



Access Management Point 441

November 30, 2021 J Matthewson Acting Department Manager Licensing and Environmental Assessment Page 20 of 20 $\,$



Access Management Point 473



Access Management Point 474

